

SmartSDR v4 Changelog

The SmartSDR™ v4 changelog lists software and firmware updates and fixes across SmartSDR for Windows, SmartSDR for the M-Models, and Maestro.

SmartSDR v4.2.18 – April 28, 2026

Feature/Defect	Description
SMART-10364	Maestro C: Iambic A is now persisted correctly
SMART-11895	DVK Preview audio is now sent to the DAX RX streams
SMART-12110	Infrastructure performance improvements for slice processing
SMART-12119	CAT/DAX: The disconnect button is now shown on the Radio chooser
SMART-12121	Global Profiles with DIV active no longer mute Slice A on FLEX-6000 Series radios
SMART-12125	Maestro F keys are now correctly assigned to DVK recordings
SMART-12135	CW Autotune function button selection is now persistent between power cycles
SMART-12138	Updated MAC resolution for DAX IQ to properly handle non-local IP addresses.
SMART-11503	Fixed APD working in a MultiFLEX environment. Now each client has an accurate state. The radio stores equalizer per frequency per power level, and both clients access the same calibration list.
SMART-12080	The TURF region is now included in the Radio Status Information
SMART-12136	Fixed an issue where the ESC child slice hears signals ~500Hz up, improving overall DIV ESC performance
SMART-12148	Fixed Fill and Gain control locations being swapped in the SmartSDR for Windows Display menu
SMART-12193	Fix an issue where radios without internet access were assigned the incorrect region
SMART-1885	Added the Czech Republic TURF Region
SMART-5318	Added South Africa TURF Region
SMART-6571	Added Portugal TURF Region
SMART-7144	Added India TURF Region
SMART-9719	Added Ireland TURF Region
SMART-12134	TURF Changes: New 60m allocation for the US
SMART-12171	Fixed the issue where the Tune button stayed blue after an interlock fault
SMART-12174	Fixed Flex API issue that stopped SmartSDR ESC parameters from updating in SDK projects
SMART-12196	Fixed issue with Aurora meters showing the wrong meter scale after band change
SMART-12220	Fixed ANF for FLEX-6000 series radios
SMART-12225	Fixed issue where the child slice audio gain always defaulted to 50 in DIV ESC
SMART-12235	Fixed Maestro error messages misspelling of 'occurred'
SMART-12194	Fixed SmartControl Power Out control with Auora Radios
SMART-12149	The FM Offset Indicator now correctly displays the direction of the frequency offset
SMART-11907	Created a 'heartbeat' indicator for APD Active and Cal to indicate cycles
SMART-12071	Updated CWX timing to improve audio "blips"

SMART-12122	Fixed receive audio not returning after transmit in CW Mode with DIV ESC enabled
SMART-12180	Improved error messaging and interaction for attempts to transmit out of band
SMART-12208	Fixed Aurora RF Output Power exceeding limits following Tune
SMART-12224	Fixed issue with no Power Out with Single Tone Tune in RTTY with two DAX IQ channels streaming
SMART-12245	Fixed an issue with Aurora where Tune and MOX incorrectly greyed out following a Band change
SMART-12250	DVK Playback now honors the Monitor setting
SMART-10349	The Maestro Frequency entry touch area has been increased
SMART-12150	SmartSDR Basic is now displayed in the License Info area (instead of None)
SMART-12260	Fixed APD Performance with Tune
SMART-7965	DAX Driver Upgrade
SMART-9674	FlexVSP Driver Upgrade
SMART-10198	Fixed various DAX Driver installation problems
SMART-10306	Fixed corrupt FlexVSP Drivers after Windows 11 updates
SMART-10665	Resolved the need to disable Windows Core Isolation to install DAX
SMART-12319	Updated Radio Setup Menu to accommodate new tabs
SMART-12023	Fixed an issue with DSP algorithms that caused glitches when adjusting parameters
SMART-11020	Fixed an issue that caused the APD button to be hidden when opening and closing the application
SMART-11492	Fixed UHE cannot access a disposed object. Object Name: 'System.Net.Sockets.Socket'
SMART-11568	Fixed various anti-virus scrutiny and Unhandled Exception errors
SMART-12014	Added toggle function for new DSP items in Maestro F-Keys Menu
SMART-12117	Fixed issues with Maestro and M Model Front Panel interface, allowing DIV child slice panning when DIV ESC was enabled
SMART-12175	Fixed UHE: Object reference not set to an instance of an object
SMART-12254	Cleaned up the Maestro TX Menu to be more cohesive
SMART-12359	Fixed an issue where DVK audio was recorded at ~1/2 speed and distorted when both multiFLEX clients had the DVK panel open
SMART-12398	Reworded menu item 'Use Low Latency Filters for Digital Modes' to 'Use Low Latency Filters for PACTOR'
SMART-12429	Fixed DVK UHE System.ArgumentOutOfRangeException
SMART-12311	Fixed an issue that would not allow the use of the internal tuner on any antenna with TGXL connected
SMART-12446	TCP client cleanup
SMART-12477	Fixed CSI CW issues
SMART-12594	Updated SmartSDR, Maestro, and M Model End User License Agreement (EULA)
SMART-12630	Fixed CW RF waveform envelope hard cutoff at the end of keying when QSK is enabled
SMART-11470	Fixed an issue where a Slice was not created following an HRESULT 0x80070490 error with PC Audio unselected
SMART-2391	Long-duration DPC "hit" no longer corrupts the DAX driver
SMART-4839	Fixed DAX: Residual or "ghosted" audio ports left in Device Manager after DAX is uninstalled. This could have caused problems during reinstallation.
SMART-8460	Fixed DAX installation issues when Core Isolation Memory Integrity is enabled
SMART-8905	Fixed DAX BSOD in portcls.sys

SMART-9970	Fixed DAX installation conflict issues with Realtek Audio Driver
SMART-11729	CAT no longer hangs when autostarted with SmartSDR on a fast PC
SMART-12129	Fixed an issue where transmitting DVK in multiFLEX did not properly return to receive when complete
SMART-12141	Turf Change: Modified Italy ITA for new 160m band allocation
SMART-12207	CAT no longer reports all interfaces as 'Not Present' when connected to an Aurora radio via Smartlink
SMART-12252	Maestro no longer disconnects from AU-520 over SmartLink when navigating to or away from 6m
SMART-12253	Maestro can now connect to Aurora Radios in SmartControl via SmartLink
SMART-12259	SmartSDR now shows the correct APD status when using Tune
SMART-12277	Fixed an issue where APD stopped working after inactivity
SMART-12288	Fixed an issue with Aurora radios not putting out full power in 10M until Tune
SMART-12364	Fixed DAX cannot connect to SmartLink radio with Auto-connect Last Radio enabled
SMART-12367	Improved DAX IQ SmartLink restriction messaging and visibility
SMART-12399	Maestro Filters menu items moved to Phone/CW Menu
SMART-12431	DAX TX Mic can now be used as the DVK recording source
SMART-12478	Fixed SmartSDR CAT UHE: There is no item (possible reason: index is too high)

SmartSDR v4.1.5 – December 16, 2025

Feature/Defect	Description
SMART-11954	Fixed an issue where toggling ESC would peg the S-meter on FLEX-6000 Series Radios
SMART-12099	Fixed DIV ESC slice audio controls to be consistent with the operation intent (SmartSDR-Win)
SMART-12118	Fixed an issue where profiles with DIV access were restored with DIV ESC enabled
SMART-12129	Fixed multiFLEX DVK playback not properly transitioning from transmit back to receive

SmartSDR v4.1.3 – December 3, 2025

Feature/Defect	Description
	Software support of the Aurora radios AU-510(M) and AU-520(M)
SMART-12007	Improved database migration between updates. It is still required to factory reset your radio after a software downgrade.
SMART-11578	Fixed NRL operational inconsistencies
SMART-11900	Fixed NR operational inconsistencies
SMART-11902	Fixed NR operation during transmit
SMART-12033	Fixed an issue where NR muted Slice B
SMART-11923	Fixed NR status message errors
SMART-11977	Fixed ANFT removing all audio when directly on top of an AM carrier
SMART-11986	Fixed ANFL not working on SSB
SMART-11987	Fixed NB for FLEX-6000 Series Radios
SMART-11744	Fixed an issue where DAX audio was briefly transmitted at the time of PTT
SMART-11799	Fixed a profile Import/Export bug
SMART-11995	Fixed the MIC and TX profile issue where not all settings were saved
SMART-11885	Fixed issue affecting FLEX-6000 Series, where a snare drum-like noise would happen when turning NR off with NRL enabled
SMART-11899	Moved the Maestro DVK menu up to just below Memory
SMART-11973	Fixed the Maestro DVK Menu needing to be scrolled to see the subscription notification
SMART-11974	Fixed Maestro DVK Menu displaying the keyboard, but not allowing edits
SMART-11998	Fixed multiple F-key selections of DVK overriding each other
SMART-11955	The Escape key now stops DVK playback in progress
SMART-12028	Improved error handling and reporting of DVK imports
SMART-12055	Improved DVK F-keys experience on Maestro
SMART-11910	Fixed the brief display issue with blank panels when launching SmartSDR
SMART-11914	Noise Mitigation options are now hidden in OPT modes on Maestro
SMART-11920	Made SmartSDR+ licensed radios show the Get SmartSDR+ button access when close to expiration for clarity
SMART-11943	Fixed error when using License Upload and clicking cancel or closing the file selection
SMART-11951	Fixed TGXL ATU Tune staying in two-tone mode (will now properly use single tone)
SMART-11954	Fixed an issue where toggling ESC would peg the S-meter on FLEX-8000 Series Radios
SMART-12021	Improved the ESC UI experience by making the child slice audio controls inaccessible
SMART-11958	Fixed ESC Slice audio panning inconsistency. Now your DIV and ESC slice audio settings will be saved independently. DIV defaults to a level of 50 with left/right pan. ESC defaults to a level of 50 panned in the center.
SMART-12019	Enabling ESC now shows the child slice as muted
SMART-11965	Resolved signal chain inconsistencies across platforms
SMART-11968	Added warning language about database/factory reset when downgrading versions
SMART-11971	Fixed Maestro DIV ESC display staying open when DIV is disabled
SMART-12000	Fixed DIV ESC not working at gain level 0

SMART-11853	Added band persistence to new noise algorithms
SMART-11926	Fixed API usage error showing agc_off_level out of bounds (1663053885) for valid levels
SMART-11952	Fixed N1MM Voice Keyer Mic command not being honored
SMART-11970	Fixed issue where APD was incorrectly displayed on FLEX-6600M
SMART-11976	Fixed missing FM options in the slice flag
SMART-12015	Added CW AutoTune to Maestro and M-Model Function Key lists
SMART-12032	Fixed an issue where RCA TX REQ inhibited transmit for the Bands not selected in TX Band Settings
SMART-12048	Added new Noise Filtering algorithms to Profiles
SMART-11304	Improved APD experience when it became inoperative after multiple power settings changes, and failed to calibrate
SMART-11953	Update EULA with Company Name, FLEX-8000 Series, and Aurora radios
SMART-10822	Fixed CW Delay settings from changing when ATU is enabled on FLEX-8000 radios
SMART-11981	Improved handling of v1 and v2 radios connecting to SmartSDR v4+
SMART-12049	Fixed an issue that would cause motorboating-like noise when adjusting XIT

SmartSDR v4.0.1 - October 30, 2025

Feature/Defect	Description
SMART-11431	<p>New DSP Noise Mitigation: We have updated and added a variety of new noise reduction/mitigation algorithms to the FLEX-6000 and 8000 series radios. The new noise mitigation features are designed to cater to different types of noises, environments, and setups. Multiple Noise Mitigation functions can be used simultaneously. Toggle the various noise mitigation functions on and off to taste.</p> <p>NRF - Spectral Subtraction Filtering Algorithm NRS - Spectral Subtraction with Voice Detection RNN - AI Noise Reduction NRL - NR algorithm using LMS (Least Mean Squares) ANFL - ANF algorithm using LMS ANFT - ANF algorithm using FFT (Fast Fourier Transform)</p>
SMART-3985	<p>Digital Voice Keyer: Digital Voice Keyer (DVK) allows recording, playback, and transmission of up to 12 voice recordings stored on the radio.</p>
SMART-10570	<p>Enhanced Signal Clarity (ESC): ESC is a unique diversity reception feature that is only available on dual SCU radios. Enhanced Signal Clarity (ESC) in diversity. ESC combines signals from multiple antennas to optimize audio receive capabilities via beamforming/null forming. Used to accentuate desired signals (constructive interference patterns) or to remove undesired signals (destructive interference patterns) to improve signal quality. This does not affect the displayed panadapter or waterfall, but metering will be affected.</p>
SMART-9958	<p>Relative Noise Floor Scaling: This feature automatically adjusts the displayed noise floor to maintain a visually consistent reference level as you operate on different bands and antennas. This feature makes it easier to compare signal strengths and visually interpret band conditions.</p>
SMART-11332	<p>CW Auto Tune: Introducing CW Auto Tune. CW Auto Tune automatically tunes the active slice receiver to CW signals within the passband, simplifying the process of locking onto CW transmissions. There are two modes of operation: One-Shot or Intermittent Mode.</p> <ul style="list-style-type: none"> • One-Shot - Auto tunes once to the highest signal on the click of the AUTOTUNE button

	<ul style="list-style-type: none"> • Intermittent – Continuously auto-tunes to the highest signal every two seconds when the AUTOTUNE button is enabled.
SMART-10956	Implemented SmartSDR+ Subscription in support of future v4.0 deployment
SMART-11309	Wide Noise Blanker (WNB) is now only accessible in the Antenna menu rather than in addition to the Slice DSP menu.
SMART-11597	Improved error logging when Tune Power is set higher than RF Power
SMART-11545	The Maestro Analog meter scale now matches other RF Power Out meters with 40, 80, 100, and 120 markings.
SMART-8466	SmartSDR now honors the locale settings and displays the appropriate date format.
SMART-11198	Fixed an issue where the PGXL Amp Temp was displayed in the wrong color
SMART-9596	Fixed an issue where the Network menu was not displayed correctly on some computers
SMART-11589	Fixed an issue where Diversity Slice did not persist configuration settings
SMART-11130	Fixed a false 10 MHz detection issue, which could result in clocking issues and a Slice being off frequency. <i>Note that External 10MHz will no longer be a source for the Auto option. When using an External 10 MHz as your clock reference, you will need to manually select the External 10 MHz option. The Clock Reference setting is now persisted over power cycles.</i>
SMART-11424	Fixed an issue where APF was not cloned properly with DIV enabled
SMART-11551	Fixed an issue where VOX could briefly trigger transmit on the wrong Slice when switching TX Slices
SMART-11556	Fixed an issue where FM Squelch would suddenly stop working
SMART-11505	Fixed APD API Status messages not changing between Active and Cal
SMART-11358	The ATU button no longer stays highlighted in the event of an ATU Tune failure.
SMART-11704	Fixed a DAX Unhandled Exception (UHE): Object not set to an instance of an object upon closing the application.
SMART-11735	Fixed an issue where the IQ Stream did not terminate after client disconnection
SMART-9103	The SmartLink Session Expired message is now worded more clearly.
SMART-11543	Fixed an issue where the peak hold meter segment would lag behind the peak meter
SMART-11734	Added percentage symbol to Max Power menu items for clarity
SMART-10948	Fixed Unhandled Error: Cannot animate the 'Text' property on a System.Windows.Controls.TextBlock
SMART-11720	Fixed the disconnect command to prevent a crash on invalid use
SMART-11773	Fixed a DotNetZip vulnerability
SMART-9084	Maestro changed the "Switch Radio" button to "Choose Radio" to be consistent with SmartSDR for Windows.
SMART-9661	Frequency range limits are now better handled by the client.
SMART-11880	ATU: 2-tone Tune option doesn't revert to single tone for ATU tune
SMART-11918	DAX IQ: Fixed the older version of the stream create command, causing incorrect byte orientation
SMART-11364	Fixed RTTY showing no RF carrier when using the TUNE feature.
SMART-9529	Tune Button no longer remains blue after Tune is deactivated due to a frequency change.
SMART-11507	APD does not recalibrate when going from TUNE to MOX at different power levels

Copyrights and Trademarks

© 2005-2025 FlexRadio. All rights reserved.

FlexRadio is a registered trademark of FlexRadio, Inc.

Aurora, FLEX-8400, FLEX-8400M, FLEX-8600, FLEX-8600M, FLEX-6300, FLEX-6400, FLEX-6400M, FLEX-6600, FLEX-6600M, FLEX-6500, FLEX-6700, FLEX-6700R, Maestro, FlexControl, SmartSDR Basic, SmartSDR+, SmartSDR, SmartSDR for Windows, SmartSDR CAT, SmartSignal, SmartLink, DAX, TNF, WNB, multiFLEX, SmartControl, FlexAdvantage, the SmartSDR “spectrum” (logo), and the FlexRadio “wave” (logo) are trademarks or servicemarks of FlexRadio, Inc.

FlexRadio, Inc.

4616 W. Howard Lane

Suite 8-860

Austin, TX USA 78728

+1 (512) 535-4713

www.flexradio.com