



FLOWDOWN REQUIREMENTS

FOREIGN OBJECT DAMAGE (FOD) PREVENTION – QUALITY ASSURANCE

Scope

The creation and maintenance of a FOD program that preserves the quality of all product coming from the seller.

Requirements

1. The seller shall ensure items supplied and the packing will not be a source of Foreign Object Damage (FOD) and/or other contaminants.
2. Seller shall establish and maintain written FOD Prevention Program Practices to reduce FOD using National Aerospace Standard 412 (NAS412), as a guideline.
 - 2.1. The FOD Prevention Program Practices shall be proportional to the FOD susceptibility of the product(s).
3. The FOD Prevention Program Practices, written procedures, or policies developed by the Seller shall be subject to review and audit by the FlexRadio and/or government representative(s).

Data Submission Summary

There is no deliverable data to FlexRadio required by this document.

Notes

N/A

Revision History

Revision 0 – Initial revision. No edits.